



BR-0025(9)B	BR 0025 9B	Federal Aid Project No.
SAP-25(62)	62	State Aid Project number
LSBP-25(9)	9	LSBP Project number
LSRP-25(1)	1	LSRP Project number
		State Aid Route
		State Aid Project
		Federal Aid Route
		State Hwy
		Supervisor District

Revised: 3-31-2026  
**Hinds County**

SAP BI 25 1	Posting
SAP 25 1	15N, 5E
SAP 25 1 M	16N, 5E
SAP 25 1 S	Reseal
SAP 25 2	15N, 4W
SAP 25 2 M	Overlay
SAP 25 2 S	Reseal
SAP 25 3	7N, 1E
SAP 25 3 M	Overlay
SAP 25 3 S	Reseal
SAP 25 4	3N, 2W
SAP 25 4 M	Overlay
SAP 25 4 S	Reseal
SAP 25 5	15N, 3W
SAP 25 5 M	Overlay
SAP 25 5 S	Reseal
SAP 25 6	6N, 2E
SAP 25 6 M	3N, 2W
SAP 25 7	6N, 1W
SAP 25 7 M	14N, 4W
SAP 25 8	5N, 4W
SAP 25 8 M	Plans not found-Sept 2025
SAP 25 9 M	7N, 1W
SAP 25 10	6N, 1W
SAP 25 12	7N, 3W
SAP 25 13	5N, 3W
SAP 25 14	5N, 2W
SAP 25 15	4N, 3W
SAP 25 16	13N, 3W
SAP 25 18	15N, 5E
SAP 25 19	3N, 2W
SAP 25 20	3N, 4W
SAP 25 21	4N, 2W
SAP 25 22	6N, 1E
SAP 25 23	5N, 1W
SAP 25 25	4N, 1W
SAP 25 27	3N, 1E
SAP 25 28	5N, 1W
SAP 25 29	7N, 2W
SAP 25 30	7N, 2W ; 6N, 2W ; 15N, 3W
SAP 25 31	3N, 2W
SAP 25 32	3N, 2W
SAP 25 33	7N, 2W
SAP 25 34	5N, 4W
SAP 25 35	5N, 3W
SAP 25 36	5N, 1W
SAP 25 37	5N, 4W
SAP 25 38	6N, 4W
SAP 25 40	14N, 5E
SAP 25 42	14N, 1W
SAP 25 43	6N, 2W
SAP 25 46	7N, 1W
SAP 25 47	4N, 1W
SAP 25 48	4N, 1W
SAP 25 50	6N, 1W
SAP 25 52	6N, 2W
SAP 25 53	3N, 3W
SAP 25 54	5N, 1W
SAP 25 55	4N, 1W
SAP 25 56	5N, 3W
SAP 25 57	6N, 1W
SAP 25 58	Removed by MS 024
SAP 25 59	4N, 1W
SAP 25 60	4N, 1W
SAP 25 61	3N, 2W
SAP 25 62	7N, 1W
SAP 25 64	7N, 2W
SAP 25 65	4N, 2W
SAP 25 66	7N, 3W
SAP 25 67	6N, 3W
SAP 25 68	7N, 1W
SAP 25 69	7N, 2W

LSBP 25 1	4N, 1W ; 5N, 1E ; 4N, 4W ; 5N, 1W
LSBP 25 2	5N, 1E
LSBP 25 3	14N, 5E
LSBP 25 4	4N, 3W ; 13N, 5E
LSBP 25 5	6N, 2E ; 4N, 4W ; 6N, 1E ; 6N, 2W ; 6N, 1W
LSBP 25 6	4N, 4W
LSBP 25 7	13N, 5E
LSBP 25 8	5N, 4W
LSBP 25 9	7N, 1W
LSBP 25 10	14N, 4W
LSBP 25 11	6N, 2W
LSBP 25 12	3N, 4W
LSBP 25 14	4N, 3W
LSBP 25 16	3N, 4W
LSBP 25 18	4N, 4W
LSBP 25 19	3N, 4W
LSBP 25 20	3N, 4W
LSBP 25 21	7N, 3W
LSBP 25 22	7N, 3W
LSBP 25 23	4N, 3W
LSBP 25 24	6N, 3W
LSBP 25 26	5N, 1E
LSBP 25 27	5N, 3W
LSBP 25 28	6N, 1W
LSBP 25 29	3N, 4W
LSBP 25 30	3N, 1W
LSBP 25 31	14N, 5E
LSBP 25 32	3N, 3W
LSBP 25 33	8N, 2W
LSBP 25 35	4N, 1W
LSBP 25 36	4N, 1W
LSBP 25 37	7N, 2W
LSBP 25 38	5N, 1W
LSBP 25 39	4N, 1W
LSBP 25 40	6N, 2E
LSBP 25 41	3N, 4W
LSBP 25 42	7N, 2W
LSBP 25 43	4N, 1W
LSBP 25 44	13N, 5E
LSBP 25 45	3N, 2W
LSBP 25 46	4N, 2W
LSBP 25 47	5N, 1W
LSBP 25 48	7N, 2W
LSBP 25 49	7N, 2W
LSBP 25 50	3N, 2W
LSBP 25 51	6N, 1W
LSBP 25 52	Plans not found-Sept 2025

BR 0025 12 B	3N, 1W
BR 0410 7 B	4N, 2W
BR 0425 2 B	4N, 1E
BR S 0407 1 B	5N, 4W
EHS SG 0410 5 B	5N, 2W
ER 0495 1 B	Plans not found-Sept 2025
HRRR 0025 24 B	Stripe
MS 024 125 1 B	Eng
MS 024 125 2 B	ROW
MS 024 125 4 B	4N, 1W
MS 024 125 7 B	4N, 1W
MS 024 125 8 B	Plans not found-Sept 2025
MS107 025 1 B	3N, 1W
MS107 025 2 B	6N, 5W
MS107 025 3 B	6N, 4W
MS107 025 4 B	3N, 4W
RRP 0025 5 B	7N, 1W
RRP 0025 10 B	3N, 1W
RRP 0415 2 B	6N, 1W
RRS 0425 1 B	4N, 1W
RSIP 0025 23 B	Signs
RSIP 0025 23 B11	Plans not found-Sept 2025
RS 0403 6 B	13N, 5E
RS 0404 3 B	15N, 5E
RS 0406 4 B	14N, 5E
RS 0415 3 B	6N, 1W
S 0404 2 1	3N, 4W
S 0405 1 B	3N, 1W
S 0406 1 B	4N, 4W
S 0406 3 B	4N, 4W
S 409 2 1	7N, 2W
S 0410 2 B	5N, 2W
S 0410 3 B	3N, 2W
S 0410 4 B	5N, 2W
S 0410 6 B	5N, 2W
S 410 2 1	6N, 1W
S 0460 2 B	5N, 1W
S 460 2 1	4N, 1W
S 0490 1 B	6N, 1W
S 0491 1 B	6N, 2W
S 0492 1 B	3N, 2W
S 0492 2 B	5N, 2W
S 0493 1 B	3N, 1W
S 0493 2 B	3N, 2W
S 0494 1 B	13N, 3W
S 0494 2 B	3N, 3W
S 0494 3 B	4N, 4W
S 1430 1 B	7N, 1W
SG 0415 1 B	6N, 1E
STP 0025 19 B	15N, 4W ; 16N, 4W
STP 0410 9 B	3N, 2W
STP 6927 1 B	5N, 2W
STPBR 0489 2B0	ERBR
PMS SRS RS 0005 025 B	Stripe
PMS 0005 125 B	Stripe