




Revised: 10-27-2025

Jasper County

BR-0075(9)B  Federal Aid Project No.
SAP-31(62)  State Aid Project number
LSBP-31(9)  LSBP Project number
LSRP-31(1)  LSRP Project number

 State Aid Route
 State Aid Project
 Federal Aid Route
 State Highway
 Supervisor District



SAP BI 31 1	Posting
SAP 31 1	1N, 12E
SAP 31 1 S	Several
SAP 31 1 TP	1N,13W; 1N,11W; 3N,11E
SAP 31 2	1N, 13W
SAP 31 2 S	Several
SAP 31 2 TP	4N,13E; 3N,13E; 2N,12E; 3N,12E; 1N,13E
SAP 31 3	4N, 11E
SAP 31 3 M	3N, 12E
SAP 31 3 S	Several
SAP 31 4	2N, 11E
SAP 31 4 M	3N, 10E
SAP 31 4 S	Several
SAP 31 5	1N, 13W
SAP 31 5 M	2N,11E; 2N,12E; 1N,13E
SAP 31 5 S	Several
SAP 31 6	4N, 13E
SAP 31 6 M	Stripe
SAP 31 6 S	Several
SAP 31 7	4N, 10E
SAP 31 7 M	1N, 11E
SAP 31 7 S	Several
SAP 31 8	2N, 11E
SAP 31 8 M	ERBR
SAP 31 8 S	1N, 10E
SAP 31 9	4N, 13E
SAP 31 9 M	2N, 13E
SAP 31 9 S	4N,11E; 10N,13W; 10N,12W
SAP 31 10	10N,10W; 3N,11E; 4N, 11E
SAP 31 10 S	Several
SAP 31 11	2N, 12E
SAP 31 11 S	Several
SAP 31 12	3N, 13E
SAP 31 12 S	Several
SAP 31 13 S	Several
SAP 31 14	1N, 13W
SAP 31 14 S	Plans not found-Oct 2025
SAP 31 15	4N, 11W
SAP 31 15 S	1N, 13E
SAP 31 16	4N, 13E
SAP 31 16 S	Plans not found-Oct 2025
SAP 31 17	2N, 13E
SAP 31 18	2N, 11E
SAP 31 19	2N, 13E
SAP 31 20	1N, 13W
SAP 31 21	2N, 11E
SAP 31 22	4N, 12E
SAP 31 23	1N, 12E
SAP 31 24	10N, 12W
SAP 31 25	4N, 11E
SAP 31 26	2N, 13E
SAP 31 27	1N, 10E
SAP 31 28	2N, 11E
SAP 31 29	4N, 10E
SAP 31 30	3N, 12E
SAP 31 31	4N, 10E
SAP 31 32	5N, 11E
SAP 31 33	2N, 11E
SAP 31 34	1N, 10E
SAP 31 35	2N, 10E
SAP 31 36	10N, 11W
SAP 31 37	4N, 12E
SAP 31 38	2N, 11E
SAP 31 39	1N, 11E
SAP 31 40	2N, 11E
SAP 31 42	1N, 12E
SAP 31 43	10N, 13W
SAP 31 45	3N, 13E
SAP 31 46	1N, 11E
SAP 31 48	1N, 10E
SAP 31 49	3N, 10E
SAP 31 51	2N, 11E
SAP 31 52	10N,11W; 10N,10W
SAP 31 54	1N, 12W
SAP 31 55	3N, 13E
SAP 31 56	10N,13W; 10N,12W
SAP 31 57	2N, 11E
SAP 31 58	4N, 13E
SAP 31 59	4N, 13E
SAP 31 60	1N, 11E
SAP 31 62	Plans not found-Oct 2025

LSBP 31 1	3N,12E; 3N,11E
LSBP 31 1 TP	2N,12E; 2N,11E
LSBP 31 2	4N, 10E
LSBP 31 3	1N, 12E
LSBP 31 4	4N,11E; 2N,10E
LSBP 31 5	2N,10E; 2N,13E
LSBP 31 6	2N, 10E
LSBP 31 8	2N, 10E
LSBP 31 9	2N, 11E
LSBP 31 10	10N, 10W
LSBP 31 11	2N, 10E
LSBP 31 12	10N, 9W
LSBP 31 13	1N, 10E
LSBP 31 14	1N, 10E
LSBP 31 15	1N, 10E
LSBP 31 16	3N, 11E
LSBP 31 17	3N, 11E
LSBP 31 18	3N, 11E
LSBP 31 19	1N, 13E
LSBP 31 20	2N, 11E
LSBP 31 21	10N, 10W

BR 0031 8 B	10N, 11E
BR 0031 10 B	3N, 10E
BR 0031 11 B	4N,10E; 2N, 10E; 1N, 13E; 10N, 12W
BR 0031 12 B	3N, 10E
BR 0031 13 B	2N, 11E
BR 0031 14 B	3N, 11E
BR 0031 15 B	4N, 13E
BR 0031 16 B	2N, 10E
BR 0031 17 B	2N, 12E
BR 0031 18 BO	2N, 10E
BR 0031 21 B	4N, 13E
BR 0234 6 B	1N, 13E
BR 1286 3 B	10N, 13E
BR 1316 2 B	10N, 12W
EHS RS 1330 2 B	3N, 11E
ER 0031 2 B	Plans not found-Oct 2025
ER 0031 20 B	Debris
HRRR 0031 22 B	1N, 13E
PLH 0439 11 B	4N, 10E
RS 0234 5 B	1N, 13E
RS 0330 12 B	3N, 10E
RS 1286 2 B	1N, 13E
RS 1330 3 B	3N, 12E
RS 1330 4 B	3N, 12E
S 0234 2 B	1N, 9W
S 0282 2 B	10N, 11W
S 0282 4 B	10N, 11W
S 0330 5 B	3N, 10E
S 0334 1 B	3N, 10E
S 0334 2 B	3N, 10E
S 0338 1 B	4N, 12E
S 339 2 1	4N, 13W
S 0359 1 B	2N, 11E
S 0366 1 B	2N, 12W
S 0366 2 B	1N, 12W
S 0366 3 B	1N, 11E
S 0368 1 B	10N, 9W
S 0381 1 B	4N, 10E
S 0381 2 B	4N, 10E
S 0381 3 B	3N, 11E
S 0381 4 B	4N,10E; 3N,11E
S 0381 5 B	3N, 11E
S 1218 3 B	10N, 13W
S 1316 1 B	1N, 10E
S 1317 1 B	10N, 10W
S 1330 1 B	3N, 11E
SOS 0031 4 B	2N, 10E
SOS 0031 5 B	3N, 13E
STP 0439 10 B	4N, 10E
STP 1218 4 B	10N, 13W
STP 1330 6 B	3N, 11E
STPBR 0031 23B	ERBR
STPG 0031 9 B	Stripe
STPG 0031 19 B	Stripe
PMS SRS RS 000S 031 B	Stripe