



BR-0058(9)B	0058(9)B	Federal Aid Project No.
SAP-58(2)	58	State Aid Project number
LSBP-58(9)	58	LSBP Project number
LSRP-58(1)	58	LSRP Project number

Green line	State Aid Route
Blue line	State Aid Project
Red line	Federal Aid Route
Purple line	State Hwy
Yellow dashed line	Supervisor District

Revised: 2-25-2026
Pontotoc County

SAP BI 58 1	Posting
SAP 58 1	10S, 4E
SAP 58 1 M	Several-resetal
SAP 58 1 S	Several
SAP 58 2	10S, 1E
SAP 58 2 M	10S, 4E
SAP 58 3	10S, 2E
SAP 58 3 M	9S, 4E
SAP 58 3 S	Several
SAP 58 4	11S, 1E
SAP 58 4 M	9S,3E; 9S,4E
SAP 58 4 S	8S,2E; 10S,1E
SAP 58 5	11S, 4E
SAP 58 5 M	Several-overlay
SAP 58 5 S	10S,4E; 10S,2E
SAP 58 6	9S, 2E
SAP 58 6 M	10S, 4E
SAP 58 6 S	11S,4E; 10S,2E
SAP 58 7	9S, 1E
SAP 58 7 M	9S,3E; 9S,2E; 10S,2E
SAP 58 7 S	10S,2E; 11S,1E
SAP 58 8	11S, 3E
SAP 58 8 M	11S,4E; 10S,4E
SAP 58 8 S	9S,2E; 9S,3E
SAP 58 9	11S, 1E
SAP 58 9 M	11S, 2E
SAP 58 9 S	Several
SAP 58 10	11S, 1E
SAP 58 10 M	9S, 2E
SAP 58 10 S	11S, 4E
SAP 58 11	10S, 1E
SAP 58 11 M	9S, 4E
SAP 58 11 S	Several
SAP 58 12	10S, 1E
SAP 58 12 M	9S, 4E
SAP 58 12 S	Several
SAP 58 13	10S, 2E
SAP 58 13 M	9S, 3E
SAP 58 13 S	Several
SAP 58 14	9S, 4E
SAP 58 14 M	8S & 9S, 1E
SAP 58 14 S	9S,4E; 9S,2E
SAP 58 15	8S, 2E
SAP 58 15 M	11S, 3E
SAP 58 15 S	Several
SAP 58 16	9S, 2E
SAP 58 16 M	Several-leveling
SAP 58 16 S	Several
SAP 58 17	9S, 4E
SAP 58 17 M	9S,1E; 10S,1E
SAP 58 17 S	Several
SAP 58 18	9S, 4E
SAP 58 18 M	9S, 4E
SAP 58 18 S	8S,2E; 11S,2E
SAP 58 19 M	10S, 2E
SAP 58 20	10S, 2E
SAP 58 20 M	Several-slurry
SAP 58 21	10S, 2E
SAP 58 21 M	10S,1E; 11S,3E
SAP 58 22	8S, 3E
SAP 58 23	8S, 3E
SAP 58 24	11S, 1E
SAP 58 25	8S, 3E
SAP 58 26	10S, 2E
SAP 58 27	10S, 4E
SAP 58 28	8S, 1E
SAP 58 29	8S, 1E
SAP 58 30	9S, 3E
SAP 58 31	11S, 2E
SAP 58 33	11S, 2E
SAP 58 34	11S, 2E
SAP 58 36	10S, 4E
SAP 58 37	9S, 4E
SAP 58 38	11S, 2E
SAP 58 39	11S, 2E

SAP 58 42	8S, 3E
SAP 58 43	8S, 1E
SAP 58 44	11S, 3E
SAP 58 45	9S, 2E
SAP 58 46	9S, 2E
SAP 58 47	10S, 4E
SAP 58 48	10S, 2E
SAP 58 49	11S, 2E
SAP 58 50	9S, 4E
SAP 58 51	11S, 2E
SAP 58 52	9S, 1E
SAP 58 53	11S, 3E
SAP 58 54	9S, 1E
SAP 58 55	8S, 4E
SAP 58 57	11S, 1E
SAP 58 58	11S, 2E
SAP 58 61	10S, 3E

LSBP 58 1	11S,2E; 9S,4E
LSBP 58 2	10S,3E; 10S,2E
LSBP 58 3	9S,4E; 9S,1E
LSBP 58 4	8S,3E; 9S,4E
LSBP 58 5	10S,3E; 9S,3E; 10S,4E
LSBP 58 6	10S, 1E
LSBP 58 8	11S, 4E
LSBP 58 9	10S, 1E
LSBP 58 10	8S, 3E
LSBP 58 11	11S, 1E
LSBP 58 12	9S, 3E
LSBP 58 13	11S, 4E
LSBP 58 14	8S, 2E
LSBP 58 15	11S, 3E
LSBP 58 16	11S, 3E
LSBP 58 17	9S, 4E
LSBP 58 18	11S, 2E
LSBP 58 19	Plans not found-Feb 2026
LSBP 58 20	9S, 4E

APL 0058 20 B	9S, 3E
APL 0058 22 B	9S, 2E
APL 9940 1 B	10S, 4E
BR 0058 8 B	8S, 2E
BR 0058 9 B	9S, 4E
BR 0058 10 B	9S, 1E
BR 0058 11 B	9S, 4E
BR 0058 12 B	10S, 4E
BR 0058 21 BO	9S, 2E
BR 0852 3 B	10S, 1E
BR 0852 4 B	10S, 1E
BR 1836 3 B	8S, 1E
BR 1884 1 B	11S, 2E
CDBG 8 1125 058 CE 01	11S, 2E
CDBG 9 1129 058 PF 01	9S, 4E
EHS RS 0856 2 B	11S, 2E
ER 0858 10 B	8S, 1E
RS 0853 9 B	10S, 4E
RS 0856 3 B	11S, 2E
RS 0858 7 B	10S, 4E
RS 1833 1 B	9S, 2E
RS 1833 2 B	9S, 2E
RS 1833 3 B	9S, 2E
RS 1886 1 B	9S, 4E
S 0852 1 B	10S, 1E
S 0852 2 B	10S, 1E
S 0856 1 B	10S, 2E
S 0858 5 B	10S, 4E
S 0874 1 B	10S, 4E
S 0876 3 B	11S, 4E
S 0876 4 B	11S, 4E
S 0894 1 B	10S, 2E
S 1836 1 B	9S, 1E
S 1836 2 B	8S, 1E
S 1886 1 B	9S, 4E
S 1886 2 B	9S, 4E
S 1883 1 B	11S, 3E
S 1897 1 B	8S, 2E
S 854 2 1	8S, 3E
S 876 2 1	11S, 4E
SRS 0058 5 B	Plans not found-Feb 2026
STP 0058 19 B	9S, 3E
STP 1833 4 B	9S, 2E
STPBR 0058 23 BO	8S, 3E
STPG 0852 5 B	Stripe
PMS SRS RS 0005 058 B	Stripe