

Attala County

Revised: 8-7-2025

State Aid Route

State Aid Project

Federal Aid Route

State HwySupervisor District

BR-0004(9)B

Federal Aid Project No.


SAP-04(62)

State Aid Project number

LSBP-04(9)

LSBP Project number

LSRP-04(1)

LSRP Project number

SAP BI 4 1	Posting
SAP 4 1	16N, 9E
SAP 4 1 M	15N,8E; 13N, 5E
SAP 4 1 S	Reseal
SAP 4 1 TP	16N, 8E
SAP 4 2	14N, 9E
SAP 4 2 S	Reseal
SAP 4 3	16N, 8E
SAP 4 3 M	Stripe
SAP 4 3 S	Reseal
SAP 4 4	13N, 4E
SAP 4 4 S	Reseal
SAP 4 5	15N, 6E
SAP 4 5 M	Stripe
SAP 4 5 S	Reseal
SAP 4 6	13N, 9E
SAP 4 6 M	14N,9E
SAP 4 6 S	Reseal
SAP 4 7	16N, 6E
SAP 4 7 S	Reseal
SAP 4 8	13N, 5E & 6E
SAP 4 8 M	14N, 5E
SAP 4 8 S	Reseal
SAP 4 9	16N, 9E
SAP 4 9 S	Reseal
SAP 4 10	16N, 7E
SAP 4 10 S	Reseal
SAP 4 11	14N, 8E
SAP 4 11 S	Reseal
SAP 4 12	14N, 7E
SAP 4 12 S	Reseal
SAP 4 13	13N, 6E
SAP 4 13 S	Reseal
SAP 4 14	15N, 6E
SAP 4 14 S	Reseal
SAP 4 15	13N, 9E
SAP 4 15 S	Reseal
SAP 4 16	16N, 6E
SAP 4 16 S	Reseal
SAP 4 17	16N, 6E
SAP 4 17 S	Reseal
SAP 4 18	12N & 13N, 4E
SAP 4 19	12N, 4E
SAP 4 20	16N, 9E
SAP 4 21	13N, 5E
SAP 4 22	13N, 5E & 6E
SAP 4 23	13N, 8E
SAP 4 25	13N, 9E
SAP 4 26	15N, 6E
SAP 4 27	13N, 4E
SAP 4 28	14N, 4E
SAP 4 29	Stripe
SAP 4 30	Stripe
SAP 4 31	16N, 8E
SAP 4 32	15N, 9E
SAP 4 33	Stripe
SAP 4 34	16N, 6E
SAP 4 36	14N, 5E
SAP 4 37	Stripe
SAP 4 38	13N, 7E
SAP 4 39	16N, 7E
SAP 4 40	16N, 6E
SAP 4 41	14N, 8E
SAP 4 43	16N, 8E
SAP 4 45	15N & 16N, 6E
SAP 4 46	15N, 8E
SAP 4 47	13N, 6E
SAP 4 48	Plans not found
SAP 4 53	16N, 7E
SAP 4 54	16N, 8E
SAP 4 55	14N, 6E
SAP 4 57	16N, 5E
SAP 4 58	16N, 8E
SAP 4 59	15N, 8E
SAP 4 60	15N, 7E
SAP 4 61	Plans not found

LSBP 4 1	13N,6E; 12N,4E; 14N, 7E
LSBP 4 2	13N,7E; 16N,9E; 15N,8E
LSBP 4 3	13N,9E; 15N,9E; 15N,5E; 12N,4E; 15N,9E
LSBP 4 4	14N, 6E
LSBP 4 5	13N,5E; 15N,7E; 16N,6E
LSBP 4 6	13N,8E; 13N, 8E; 15N,9E
LSBP 4 7	13N,5E; 13N,7E; 14N,8E; 14N,7E; 15N,5E
LSBP 4 8	14N,6E; 13N,8E; 13N,9E; 16N,9E
LSBP 4 9	15N, 7E
LSBP 4 10	12N, 4E
LSBP 4 11	14N,8E; 16N,9E
LSBP 4 12	15N,6E; 14N,5E
LSBP 4 13	13N,9E; 16N,9E
LSBP 4 14	15N,6E; 13N,6E
LSBP 4 15	Plans not found
LSBP 4 16	15N, 5E
LSBP 4 17	13N, 5E
LSBP 4 18	15N,9E; 15N,8E
LSBP 4 19	Plans not found
LSBP 4 21	16N, 6E
LSBP 4 22	14N, 5E
LSBP 4 23	Plans not found

BR 0004 10 B	15N, 7E
BR 0004 12 B	14N, 5E & 6E
BR 0004 13 BO	14N, 8E
BR 0004 16 B	13N, 9E
BR 0004 18 B	16N, 6E & 7E
BR 0004 20 B	15N, 6E
BR 0661 5 B	16N, 6E
BR 0664 3 B	16N, 8E
BR 1620 1 B	13N, 9E
BR 1621 1 B	14N, 7E
EHS S 1618 2 B	13N, 7E & 8E
ER 0004 8 B	Plans not found
ER 0685 2 B	15N, 8E
ER 1624 1 B	13N, 4E
MS105 004 1 B	14N, 5E
MS105 004 2 B	14N, 7E
MS105 004 3 B	15N, 8E
RS 0004 7 B	14N, 9E
RS 0644 4 B	13N, 7E
RS 0644 6 B	13N, 8E
RS 0685 5 B	15N, 8E
RS 0722 2 B	16N, 8E & 9E
RS 1624 3 B	14N, 4E
S 0644 3 B	13N, 8E
S 0661 1 B	16N, 6E & 7E
S 0661 2 B	16N, 7E
S 0661 3 B	16N, 6E
S 0662 3 B	16N, 6E
S 0664 1 B	16N, 8E
S 0664 2 B	16N, 8E
S 0667 1 B	13N, 6E
S 0668 1 B	14N, 6E
S 0669 1 B	14N, 8E
S 0686 1 B	13N, 9E
S 0686 2 B	15N, 8E
S 1618 1 B	13N, 8E
S 644 2 1	13N, 8E
S 656 2 1	13N, 4E
SRS 0004 2 B	Eng
STP 0004 17 B	Reseal
STP 0004 19 B	Reseal
STP 1624 4 B	14N, 6E
STPBR 0722 7 BO	ERBR
PMS SRS RS 000S 004 B	Stripe
PMS 000S 104 B	Stripe