



- BR-0012(9)B Federal Aid Project No.
- SAP-12(62) State Aid Project No.
- LSBP-12(9) LSBP Project number
- LSRP-12(1) LSRP Project number
- State Aid Route
- State Aid Project
- Federal Aid Route
- State Hwy
- Supervisor District

Revised: 4-10-2026  
**Clarke County**

SAP BI 12 1	Posting
SAP 12 1	2N, 17E
SAP 12 1 S	Reseal
SAP 12 2	4N, 17E
SAP 12 2 M	2N, 15E
SAP 12 2 S	Reseal
SAP 12 3	1N, 14E
SAP 12 3 M	Stripe
SAP 12 3 S	Reseal
SAP 12 4	4N, 17E
SAP 12 4 M	1N, 14E
SAP 12 4 S	Reseal
SAP 12 5 S	Reseal
SAP 12 6 M	2N, 15E
SAP 12 6 S	Reseal
SAP 12 7	4N, 14E
SAP 12 7 S	Reseal
SAP 12 8	2N, 16E
SAP 12 8 S	Reseal
SAP 12 9	4N, 17E
SAP 12 9 S	Reseal
SAP 12 10	3N, 16E
SAP 12 10 S	Reseal
SAP 12 11	3N, 14E
SAP 12 11 S	Reseal
SAP 12 12 S	Reseal
SAP 12 13	2N & 3N, 16E
SAP 12 13 S	Reseal
SAP 12 14	4N, 17E
SAP 12 14 S	Reseal
SAP 12 15	2N & 3N, 16E
SAP 12 15 S	Reseal
SAP 12 16	4N, 15E
SAP 12 16 S	Reseal
SAP 12 17	10N, 8W
SAP 12 17 S	Reseal
SAP 12 18	4N, 14E
SAP 12 18 S	Reseal
SAP 12 19	4N, 14E
SAP 12 20	1N, 14E
SAP 12 20 S	Reseal
SAP 12 21 S	Plans not found-Aug 2025
SAP 12 22	1N, 17E
SAP 12 23	3N, 17E
SAP 12 24	3N, 15E
SAP 12 25	3N, 14E
SAP 12 26	3N, 15E
SAP 12 27	1N, 14E
SAP 12 28	3N & 4N, 17E
SAP 12 30	10N, 7W
SAP 12 33	2N, 16E
SAP 12 34	3N, 14E
SAP 12 35	1N, 14E
SAP 12 42	2N, 15E
SAP 12 43	10N, 9W ; 2N, 16E ; 10N, 7W
SAP 12 44	4N, 14E
SAP 12 45	3N, 16E
SAP 12 46	3N, 15E ; 4N, 15E
SAP 12 47	1N, 14E
SAP 12 49	4N, 14E
SAP 12 50	4N, 15E
SAP 12 51	1N, 14E
SAP 12 52	4N, 16E
SAP 12 53	1N, 15E
SAP 12 54	10N, 15E
SAP 12 55	3N, 15E
SAP 12 56	2N, 16E
SAP 12 57	2N, 15E
SAP 12 58	4N, 14E
SAP 12 59	4N, 18E
SAP 12 62	4N, 17E
SAP 12 64	4N, 14E
SAP 12 65	3N, 15E
SAP 12 66 TP	Timber
SAP 12 67	3N, 16E
SAP 12 68 TP	4N, 17E ; 4N, 18E
SAP 12 69	Plans not found-Aug 2025
SAP 12 70	10N, 7E
SAP 12 71	Plans not found-Aug 2025

LSBP 12 1	4N, 17E
LSBP 12 2	2N, 14E ; 1N, 17E
LSBP 12 3	3N, 14E
LSBP 12 4	4N, 17E
LSBP 12 5	3N, 17E ; 1N, 17E ; 2N, 14E
LSBP 12 6	3N, 16E
LSBP 12 7	2N, 17E
LSBP 12 8	2N, 14E
LSBP 12 9	1N, 15E
LSBP 12 10	1N, 15E
LSBP 12 11	3N, 15E
LSBP 12 12	1N, 15E
LSBP 12 13	2N, 17E ; 4N, 16E
LSBP 12 14	2N, 17E
LSBP 12 15	3N, 16E
LSBP 12 16	Plans not found-Aug 2025
LSBP 12 17	4N, 16E

BR 0012 12 B	1N, 14E
BR 0012 14 B	5N, 15E
BR 0012 23 B	3N, 16E ; 4N, 16E
BR 0346 4 B	2N, 17E
BR 0346 5 B	2N, 17E
BR 0348 8 B	5N, 18E
BR 1331 2 B	2N, 15E
BR 1331 5 BO	3N, 14E
BR S 1331 1 B	3N, 14E
DS 0348 3 B	4N, 18E
ER 0012 2 B	Plans not found-Aug 2025
ER 0342 4 B	2N, 16E
ER 51 1	Plans not found-Aug 2025
ER 51 2	Plans not found-Aug 2025
ER 51 3	2N, 17E
HRRR 0012 26 B	Guard rail
RRP 0012 5 B	4N, 15E
RRP 0012 11 B	4N, 14E
RS 0234 4 B	10N, 8W
RS 0345 3 B	2N, 16E
RS 0348 6 B	4N, 16E
RS 0348 7 B	4N, 17E
RS 0376 1 B	2N, 17E
RS 1331 4 B	3N, 15E
S 0340 2 B	4N, 14E
S 0342 2 B	1N, 14E
S 0342 3 B	2N, 16E
S 0343 2 B	1N & 10N, 7W
S 0344 1 B	10N, 9W
S 0344 3 B	1N, 9W
S 0344 5 B	10N, 7W
S 0345 1 B	1N, 17E
S 0345 2 B	1N, 18E
S 0346 2 B	1N, 18E
S 0347 1 B	3N, 18E
S 0347 2 B	4N, 18E
S 0348 2 B	4N, 17E
S 0357 1 B	1N, 15E
S 0357 2 B	1N, 14E
S 0358 2 B	3N, 15E
S 0370 1 B	3N, 16E
S 0370 2 B	5N, 15E
S 0374 1 B	4N, 15E
S 0374 2 B	4N, 15E
S 0375 1 B	2N, 17E
S 1230 1 B	1N, 17E
S 1230 2 B	1N, 17E
S 342 2 1	1N, 15E
S 343 2 1	1N, 8W
S 346 2 1	2N, 17E
S 348 2 1	4N, 16E
S 358 2 1	3N, 15E
SR 0346 3 B	2N, 17E
STP 0012 19 B-S	4N, 14E
STP 0342 5 B	1N, 14E
STP 0345 4 B-S	2N, 15E
STP 0376 2 B	2N, 16E
STPBR 0346 7 B	Plans not found-Aug 2025
STPG 0012 18 B	Stripe
PMS SRS RS 000S 012 B	Stripe