




Revised: 8-21-2025

Clay County

State Aid Route

State Aid Project

Federal Aid Route

State Hwy

Supervisor District

BR-0013(9)B

Federal Aid Project No.

SAP-13(2)

State Aid Project Number

LSBP-13(9)

LSBP Project Number

LSRP-13(1)

LSRP Project Number

LPG-13(9)

LPG Project number

SAP BI 13 1	Posting
SAP 13 1	17S, 16E
SAP 13 1 M	16S,13E ; 20N,16E ; 16S,4E
SAP 13 1 S	Reseal
SAP 13 2	17S, 7E
SAP 13 2 M	20N, 13E
SAP 13 2 S	Reseal
SAP 13 3	15S, 15E
SAP 13 3 M	Stripe
SAP 13 3 S	Reseal
SAP 13 4	20N, 13E
SAP 13 4 M	17S,7E ; 16S,3E
SAP 13 4 S	Reseal
SAP 13 5	17S, 6E
SAP 13 5 M	Stripe
SAP 13 5 S	Reseal
SAP 13 6	15S, 4E
SAP 13 6 M	15S & 16S, 13E
SAP 13 6 S	Reseal
SAP 13 7	16S, 4E
SAP 13 7 M	UHMA
SAP 13 7 S	Reseal
SAP 13 8	15S, 5E
SAP 13 8 M	Stripe
SAP 13 8 S	Reseal
SAP 13 9	17S, 6E
SAP 13 9 S	Reseal
SAP 13 10	19N, 16E
SAP 13 10 M	Overlay
SAP 13 10 S	Reseal
SAP 13 11	20N, 13E
SAP 13 11 M	16S, 6E
SAP 13 11 S	Reseal
SAP 13 12	17S, 7E
SAP 13 12 M	Overlay
SAP 13 12 S	Reseal
SAP 13 13	19N, 16E
SAP 13 13 M	Plans not found-Aug 2025
SAP 13 13 S	Reseal
SAP 13 14	20N, 16E
SAP 13 14 S	Reseal
SAP 13 15	17S, 5E
SAP 13 15 S	Reseal
SAP 13 16	16S, 6E
SAP 13 17	16S, 6E
SAP 13 18	20N, 13E
SAP 13 19	17S, 5E
SAP 13 20	17S, 5E
SAP 13 21	17S, 7E
SAP 13 22	16S, 7E
SAP 13 23	15S, 5E
SAP 13 24	16S, 7E
SAP 13 26	17N,6E
SAP 13 27	15S, 5E
SAP 13 29	15S, 4E
SAP 13 30	17S, 6E
SAP 13 31	16S, 5E
SAP 13 33	16S, 3E
SAP 13 34	20N, 14E
SAP 13 35	15S, 3E
SAP 13 36	15S, 3E
SAP 13 37	17S, 6E
SAP 13 38	19N, 16E
SAP 13 39	ERBR

LPG 13 1	17S, 6E
LPG 13 2 O	17S, 6E
LPG 13 3 O	17S, 6E
LPG 13 4	17S, 7E
LPG 13 5 O	17S, 7E
LPG 13 6 O	17S, 6E
LPG 13 7	17S,6E ; 17S,7E ; 17S,8E
LPG 13 8 O	17S, 6E
LPG 13 11	17S, 6E

LSBP 13 1	15S,5E ; 16S,3E ; 16S,4E
LSBP 13 2	20N, 13E
LSBP 13 3	17S, 6E
LSBP 13 4	20S, 12E
LSBP 13 5	16S,7E ; 16S,3E ; 16S,3E
LSBP 13 6	16S,3E ; 17S,7E
LSBP 13 7	16S,3E ; 16S,6E
LSBP 13 8	16S, 4E
LSBP 13 9	15S, 4E
LSBP 13 10	16S, 3E
LSBP 13 11	17S, 5E
LSBP 13 12	15S, 4E
LSBP 13 13	17S, 5E
LSBP 13 15	16S, 4E
LSBP 13 16	16S, 6E
LSBP 13 17	Plans not found-Aug 2025

AHL 0013 18 B	17S, 7E
APL 0013 11 B	20N, 16E
APL 0013 31 B	16S, 3E
APL 0013 33 B	16S, 3E
APL 0013 42 B	17S, 7E
APL 0013 46 B	17S, 6E
APL 0744 4 B	15S, 5E
APL 1716 5 B	21N, 3E
APL 9964 1 B	17S, 6E
APL 9999 1 B	17S, 6E
BR 0013 13 B	16S, 5E
BR 0013 14 B	17S, 7E
BR 0013 16 B	17S, 7E
BR 0013 27 B	16S, 6E
BR 0013 28 B	17S, 6E
BR 0013 32 B	16S, 3E
BR 0013 34 B	16S, 4E
BR 0013 35 B	16S, 3E
BR 0013 36 B	18S, 16E
BR 0013 37 B	20N,13E ; 15S,5E ; 16S,4E ; 16S,6E
BR 0013 38 BO	16S,3E ; 16S,7E
BR 0013 40 BO	16S,13E ; 16S,5E
BR 0013 41 BO	16S,3E ; 16S,4E
BR 0013 45 BO	16S, 7E
BR 0013 49 BO	20N, 12E
BR 0739 12 B	20N, 13E
BR 0739 18 B	21N, 13E
BR 0739 19 B	12S, 3E
BR 0739 20 B	21N, 3E
BR 0744 6 B	15S, 5E
BR 0744 7 B	15S, 5E
BR 0744 9 B	15S, 5E
BR 0744 10 B	15S, 5E
BR 0770 3 B	15S, 5E
BR 0770 4 B	16S, 5E
DECD 0013 51 B	16S, 6E
DECD 0013 52 BI	17S, 7E
DECD 0013 52 BI1	17S, 7E
ER 0013 2 B	Plans not found-Aug 2025
RRP 0013 20 B	17S, 6E
RRP 0013 22 B	17S, 6E
RRP 0739 15 B	20N, 13E
RRS 0013 19 B	17S, 6E
RRS 0013 21 B	17S, 6E
RRS 0739 16 B	20N, 13E
RS 0739 10 B	20N, 13E
RS 0739 11 B	21N, 13E
RS 1715 2 B	17S, 7E
RS 1715 5 B	17S, 7E
S 0739 2 B	20S, 13E
S 0770 1 B	16S, 5E
S 0770 2 B	16S, 5E
S 0771 1 B	17S, 6E
S 1714 1 B	17S, 7E
S 1714 2 B	17S, 7E
S 1715 1 B	17S, 6E
S 1716 1 B	21N, 3E
S 1716 2 B	20N, 14E
S 1716 3 B	20N, 14E
S 1716 4 B	20N, 13E
S 739 2 1	20S, 13E
S 744 2 1	15S, 15E
SEGC 0744 8 B	15S, 4E
SEGC 1715 6 B	18S, 6E
SOS 0013 5 B	17S, 5E
SOS 0013 6 B	15S, 5E
SOS 0013 9 B	17S, 6E
SOSG 0013 7 B	17S, 6E
SRS 0013 4 B	Eng

STP 0013 23 B-S	16S, 6E
STP 0013 24 B-C	16S, 6E
STP 0013 25 B-C	19N, 16E
STP 0013 26 B-S	19N, 16E
STP 0013 47 BO	15S, 3E
STP 0140 3 B	16S, 6E
STP 0140 4 B	16S, 6E
STP 0736 2 B	19N, 16E
STP 0739 23 B	16S, 3E
STP 0744 11 B	15S, 4E
STP 1715 7 B	17S, 7E
STPBR 0013 53 B	ERBR
STPBR 0770 5B	15S, 5E
STPD 0013 44 B	Eng
STP-EGC 0739 22 B	20N, 13E
TQS 1715 4 B	17S, 7E
PMS SRS RS 000S 013 B	Stripe