



BR-0017(9)B Federal Aid Project No.  
 SAP-17(62) State Aid Project number  
 LSBP-17(9) LSBP Project number  
 LSRP-17(1) LSRP Project number  
 State Aid Route  
 State Aid Project  
 Federal Aid Route  
 State Hwy  
 Supervisor District

Revised: 3-31-2026  
**Desoto County**

SAP BI 17 1	Posting
SAP 17 1	2S, 8W
SAP 17 1 M	Stripe
SAP 17 1 S	Reseal
SAP 17 2	3S, 9W
SAP 17 2 M	3S,7W ; 1S,5W
SAP 17 2 S	Reseal
SAP 17 3	2S, 5W
SAP 17 3 M	3S, 8W
SAP 17 3 S	Reseal
SAP 17 4	3S, 7W
SAP 17 4 M	3S,7W ; 3S,6W
SAP 17 4 S	Reseal
SAP 17 5	2S, 6W
SAP 17 5 M	3S,8W ; 1S,7W
SAP 17 5 S	Reseal
SAP 17 6	2S, 9W
SAP 17 6 M	2S, 9W
SAP 17 7	3S, 8W
SAP 17 7 M	2S,5W ; 1S,5W
SAP 17 8	3S, 8W
SAP 17 8 M	Box extension & Pipe
SAP 17 9	3S, 7W
SAP 17 9 M	3S, 7W
SAP 17 10	3S, 6W
SAP 17 10 M	2S, 6W
SAP 17 11	1S, 7W
SAP 17 11 M	1S, 9W
SAP 17 12	3S, 7W
SAP 17 12 M	2S,8W ; 1S,8W
SAP 17 13	1S, 9W
SAP 17 13 M	1S,5W ; 2S,7W
SAP 17 14	2S, 9W
SAP 17 14 M	2S,7W ; 2S,5W
SAP 17 15	2S, 8W
SAP 17 15 M	Overlay
SAP 17 16	2S, 6W
SAP 17 16 M	3S,7W ; 3S,8W
SAP 17 20	1S, 9W
SAP 17 21	1S, 7W
SAP 17 22	1S, 7W
SAP 17 23	1S, 5W
SAP 17 24	2S, 8W
SAP 17 26	1S, 9W
SAP 17 28	3S, 7W
SAP 17 31	2S, 7W
SAP 17 33	2S, 8W
SAP 17 34	3S, 7W
SAP 17 35	3S, 9W
SAP 17 39	2S, 8W
SAP 17 41	2S, 7W
SAP 17 42	3S, 5W
SAP 17 43	1S, 8W
SAP 17 44	1S, 8W
SAP 17 45	3S, 5W
SAP 17 46	2S, 7W
SAP 17 47	2S, 8W
SAP 17 48	2S, 7W
SAP 17 50	1S, 8W
SAP 17 51	2S, 7W
SAP 17 52	2S, 7W
SAP 17 53	2S, 8W
SAP 17 54	3S,8W ; 2S,8W
SAP 17 55	2S, 7W
SAP 17 56	3S, 6W

LSBP 17 1	1S,6W ; 3S,8W
LSBP 17 2	2S,10W ; 2S,9W ; 3S,9W ; 3S,8W ; 4S,7W
LSBP 17 4	3S,6W ; 4S,7W ; 2S,9W
LSBP 17 5	2S, 6W
LSBP 17 6	1S, 8W
LSBP 17 7	1S, 8W
LSBP 17 8	Plans not found- Aug 2025
LSRP 17 1	2S, 8W

BR 0017 14 B	3S, 10W
BR 0017 15 B	3S, 7W
BR 0017 16 B	2S, 10W
BR 0017 17 B	3S, 5W
BR 0017 24 BO	2S, 8W
BR 0017 25 B	3S, 5W
BR 0017 26 BO	2S, 6W
BR 0017 47 B	2S, 8W
BR 0974 5 B	2S, 6W
BR 0974 6 B	2S, 7W
BR 0975 2 B	3S, 5W
BR 0976 5 B	Plans not found- Aug 2025
BR 1920 4 B	3S, 7W
BR 1946 3 B	2S, 9W
BR 1964 5 B	3S, 9W
BR 1966 4 B	3S, 6W
BR 1966 5 B	3S, 6W
BR 7860 4 B	1S, 8W
DECD 0017 28 B	1S, 6W
DECD 0017 29 B	1S, 6W
DECD 0017 30 B	2S, 6W
DECD 0017 31 B	1S, 8W
DECD 0017 33 B	1S, 8W
DECD 0017 34 B	1S, 8W
DECD 0017 35 B	2S, 7W
DECD 0017 36 B	2S, 7W
DECD 0017 38 B	2S, 7W
DECD 0017 39 B	2S, 7W
DECD 0017 40 B	2S, 7W
DECD 0017 42 B	1S, 7W
DECD 0017 44 B	1S, 8W
DECD 0017 48 B	2S, 6W
ER 0017 2 B	Plans not found- Aug 2025
ER 0017 3 B	3S,7W ; 3S,6W ; 2S,7W ; 3S,6W
ER 0975 2 B	3S, 6W
RRO 0017 9 B	1S, 6W
RRP 0017 18 B	2S, 8W
RRP 0017 19 B	1S, 9W
RRP 0017 20 B	1S, 9W
RRP 0017 21 B	1S, 9W
RRP 0017 22 B	2S, 5W
RRP 0017 23 B	2S, 5W
RRP 1947 2 B	Plans not found- Aug 2025
RRS 1969 1 B	2S, 6W
RRS 9227 2 B	2S, 8W
RS 1920 3 B	3S, 7W
RS 1944 2 B	3S, 8W
RS 1945 1 B	1S, 7W
RS 1945 2 B	1S, 7W
RS 1946 2 B	2S, 7W
RS 1964 6 B	4S, 9W
RS 1966 3 B	3S, 6W
S 0905 3 B	1S, 8W
S 0905 5 B	1S, 6W
S 0905 6 B	1S, 7W
S 0905 9 B	1S, 5W
S 0906 2 B	2S, 9W
S 0975 1 B	3S, 6W
S 0978 1 B	3S, 9W
S 1920 2 B	3S, 7W
S 1944 1 B	3S, 8W
S 1946 1 B	2S, 8W
S 1964 1 B	4S, 9W
S 1966 1 B	3S, 8W
S 1966 2 B	4S, 8W
S 905 2 1	1S, 8W
SG 0905 2 B	Plans not found- Aug 2025
SG 0906 1 B	2S, 10W
SG 0974 1 B	2S, 8W
SG 0974 2 B	Plans not found- Aug 2025
SOS 0017 5 B	2S, 7W
SOS 0017 6 B	2S, 7W
SOS 0017 10 B	2S, 8W

STP 0017 27 B-S	3S, 7W
STP 0906 3 B	2S, 8W
STP 0906 4 B	ERBR
STP 1946 4 B	2S, 9W
STP 1964 8 B	4S, 9W
STP 1966 7 B	3S, 5W
STP 1969 2 B	2S, 6W
STPD 1920 6 B	3S, 6W
MDAH 0017 1 B	Indian Mound
PMS SRS RS 000S 017 B	Stripe
PMS 000S 117 B	Stripe