



SAP-26(62)	62	State Aid Project number
LSBP-26(9)	9	LSBP Project number
LSRP-26(1)	1	LSRP Project number
		State Aid Route
		State Aid Project
		Federal Aid Route
		State Hwy
		Supervisor District

Revised: 3-31-2026
Holmes County

SAP BI 26 1	Posting
SAP 26 1	14N, 1W
SAP 26 1 M	13N,1E; 14N,4E
SAP 26 1 S	Reseal
SAP 26 2	14N, 3W
SAP 26 2 M	Overlay
SAP 26 2 S	Reseal
SAP 26 3	16N,4E; 16N,5E
SAP 26 3 M	14N, 2E
SAP 26 3 S	Reseal
SAP 26 4 M	Stripe
SAP 26 4 S	Reseal
SAP 26 5	14N, 2E
SAP 26 5 S	Reseal
SAP 26 6	14N, 1E
SAP 26 6 M	16N, 1W
SAP 26 6 S	Reseal
SAP 26 7	16N, 4E
SAP 26 7 M	13N, 1E
SAP 26 7 S	Reseal
SAP 26 8	14N, 1E
SAP 26 8 M	15N, 3E
SAP 26 8 S	Reseal
SAP 26 9	14N, 1E
SAP 26 9 S	Reseal
SAP 26 10	15N, 1W
SAP 26 10 M	Overlay
SAP 26 10 S	Reseal
SAP 26 11 M	14N,2E; 17N,2E
SAP 26 11 S	Reseal
SAP 26 12	13N, 2E
SAP 26 12 M	Overlay
SAP 26 12 S	Reseal
SAP 26 13	13N, 2E
SAP 26 13 M	13N, 2E
SAP 26 13 S	Reseal
SAP 26 14	14N, 2E
SAP 26 14 M	17N, 1W
SAP 26 15	14N, 2W
SAP 26 15 S	Reseal
SAP 26 16	14N, 2W
SAP 26 16 S	Reseal
SAP 26 17	13N, 1E
SAP 26 17 S	Reseal
SAP 26 18	16N, 1W
SAP 26 18 S	Reseal
SAP 26 19	13N, 1E
SAP 26 19 S	Reseal
SAP 26 20	16N, 1W
SAP 26 20 S	Reseal
SAP 26 21	13N, 3E
SAP 26 22	15N, 2E
SAP 26 23	15N, 1E
SAP 26 24	15N, 1E
SAP 26 25	14N, 2E
SAP 26 26	13N, 2E
SAP 26 27	14N, 2E
SAP 26 28	14N, 3E
SAP 26 29	15N, 2E
SAP 26 30	16N, 1E
SAP 26 31	13N, 2E
SAP 26 32	14N, 1E
SAP 26 33	15N, 4E
SAP 26 35	16N, 1E
SAP 26 36	15N, 4E
SAP 26 37	16N, 1E
SAP 26 38	13N, 2E
SAP 26 39	16N, 3E
SAP 26 40	16N, 3E
SAP 26 41	13N, 2E
SAP 26 42	14N, 2E
SAP 26 43	14N, 2E
SAP 26 44	14N, 2E
SAP 26 45	16N, 4E
SAP 26 47	15N, 1E
SAP 26 48	14N, 1W
SAP 26 49	16N, 4E

SAP 26 50	14N, 2W
SAP 26 51	16N, 2E
SAP 26 52	13N, 3E
SAP 26 53	14N, 1E
SAP 26 55	13N, 2E
SAP 26 56	15N, 2E
SAP 26 57	16N, 4E
SAP 26 58	15N, 2E
SAP 26 59	13N, 2E
SAP 26 60	17N, 2E
SAP 26 61	17N, 2E
SAP 26 62	13N, 1E
SAP 26 63	14N, 2W
SAP 26 64	15N, 1W
SAP 26 65	16N,3E; 16N,4E; 17N,1E
SAP 26 66	16N, 2E
SAP 26 67	14N, 2E
SAP 26 68	13N, 1E
SAP 26 70	15N, 1E
SAP 26 71	15N, 4E
SAP 26 72	15N, 3E
SAP 26 73	15N, 4E

LSBP 26 1	15N,4E; 13N,3E; 17N,1E; 15N,4E; 15N,3E
LSBP 26 2	15N, 1E; 13N, 3E; 16N, 3E; 15N, 2E; 16N, 3E
LSBP 26 3	15N,4E; 14N,4E; 14N,4E; 13N,3E; 14N,2E
LSBP 26 4	16N, 1E; 16N, 3E
LSBP 26 5	14N, 2E; 14N, 3E
LSBP 26 6	14N, 4E
LSBP 26 7	16N, 4E
LSBP 26 8	17N, 1E
LSBP 26 9	15N, 1E
LSBP 26 10	14N, 3E
LSBP 26 11	13N, 2E
LSBP 26 12	13N, 1E
LSBP 26 13	15N, 4E
LSBP 26 14	15N, 4E
LSBP 26 15	13N, 1E
LSBP 26 16	14N, 1E
LSBP 26 17	13N, 1E
LSBP 26 18	16N, 4E
LSBP 26 19	13N, 2E
LSBP 26 20	16N, 3E
LSBP 26 21	Plans not found-Oct 2025

BR 0026 3 B	14N, 2W
BR 0026 4 BO	14N, 1W
BR 0026 5 B	12N, 3E
BR 0026 6 BO	13N,1E; 14N,1E; 15N,4E; 15N,1E
BR 0026 7 B	15N, 1E
BR 0635 7 B	14N, 1E
BR 0689 1 B	14N, 3E
BR 0692 3 B	17N, 2E
ER 0655 1 B	15N, 1E
MS096 026 1 B	Eng
MS096 026 2 B	17N, 2E
MS096 026 3 B	13N, 4E
MS096 026 4 B	12N, 3E
MS096 026 5 B	Plans not found-Oct 2025
RS 0637 2 B	13N, 2E
RS 0690 1 B	16N, 4E
RS 0691 1 B	14N, 1E
RS 0692 1 B	17N, 1W
RS 0692 2 B	17N, 1W
RS 1635 1 B	17N, 1E
S 506 2 1	13N & 14N, 2E
S 506 2 2	14N, 2E
S 0506 13 B	13N, 2E
S 0600 2 B	Plans not found-Oct 2025
S 633 2 1	17N, 1W
S 0633 2 B	17N, 1E
S 0634 1 B	15N, 1E
S 0634 2 B	16N, 1W
S 0635 1 B	14N, 1E
S 0635 2 B	14N, 2E
S 0635 3 B	14N, 1W
S 0635 4 B	14N, 1W
S 0635 5 B	15N, 1E
S 0637 1 B	14N, 2E
S 0638 1 B	13N, 1E
S 0639 1 B	14N, 4E
S 0640 1 B	15N, 3E & 4E
S 0640 2 B	15N, 3E & 4E
S 0640 3 B	15N, 3E
S 642 2 1	16N, 5E
S 0642 11 B	16N, 4E
S 0642 18 B	16N, 4E
S 0642 20 B	16N, 4E
S 0660 1 B	14N, 2W
S 1634 1 B	15N, 1W
STP 0506 20 B	14N, 2E
STP 0638 3 B	13N, 2E
PMS SRS RS 0005 026 B	Stripe
PMS 000S 126 B	Stripe