




- State Aid Route
- State Aid Project
- Federal Aid Route
- State Hwy
- Supervisor District

- BR-0033(9) Federal Aid Project No.
- SAP-33(62) State Aid Project Number
- LSBP-33(9) LSBP Project Number
- LSRP-33(1) LSRP Project Number

Revised: 11-4-2025

Jefferson Davis

SAP BI 33 1	Posting
SAP 33 1	9N, 18W
SAP 33 1 M	6N,18W; 6N,19W; 7N,17W; 7N,18W; 9N,19W
SAP 33 1 S	9N, 18W
SAP 33 2	6N, 17W
SAP 33 2 M	Overlay, Several
SAP 33 2 S	7N,17W; 9N,18W; 9N,19W
SAP 33 3	9N, 19W
SAP 33 3 M	7N,18W; 8N,19W
SAP 33 3 S	7N, 18W
SAP 33 4	9N, 19W
SAP 33 4 M	Several
SAP 33 4 S	6N, 18W
SAP 33 5	7N, 18W
SAP 33 5 M	7N, 16W
SAP 33 5 S	Several
SAP 33 6	9N, 19W
SAP 33 6 M	6N,18W; 7N,18W; 7N,19W
SAP 33 6 S	9N,18W; 7N,19W
SAP 33 7	8N, 18W
SAP 33 7 M	Stripe
SAP 33 7 S	9N, 19W
SAP 33 8	7N, 16W
SAP 33 8 M	6N, 19W
SAP 33 8 S	Several
SAP 33 9	7N, 16W
SAP 33 9 M	Drainage, Several
SAP 33 9 S	Several
SAP 33 10	7N, 16W
SAP 33 10 M	Stripe
SAP 33 10 S	Several
SAP 33 11 M	7N, 16W
SAP 33 11 S	5N, 19W
SAP 33 12	7N, 17W
SAP 33 12 M	7N, 17W
SAP 33 12 S	Several
SAP 33 13	8N, 18W
SAP 33 13 M	Stripe
SAP 33 13 S	Several
SAP 33 14	6N, 17W
SAP 33 14 M	9N, 19W
SAP 33 14 S	Several
SAP 33 15	6N, 17W
SAP 33 15 M	9N, 19W
SAP 33 15 S	Several
SAP 33 16	7N, 18W
SAP 33 16 M	5N,19W; 8N,19W
SAP 33 16 S	Several
SAP 33 17	9N, 19W
SAP 33 17 M	7N, 19W
SAP 33 17 S	Several
SAP 33 18	9N, 18W
SAP 33 18 M	Micro, Several
SAP 33 18 S	Several
SAP 33 19	7N, 16W
SAP 33 19 M	7N, 16W
SAP 33 19 S	Plans not found-Nov 2025
SAP 33 20	7N, 19W
SAP 33 20 M	6N,16W; 9N,19W
SAP 33 21	7N, 20W
SAP 33 22	8N, 18W
SAP 33 22 M	Plans not found-Nov 2025
SAP 33 24	8N, 19W
SAP 33 25	6N, 16W
SAP 33 26	8N, 18W
SAP 33 27	7N, 20W
SAP 33 28	6N, 19W
SAP 33 29	7N, 16W
SAP 33 30	6N, 16W
SAP 33 31	7N, 18W
SAP 33 32	8N, 18W
SAP 33 33	6N,18W; 7N,18W
SAP 33 34	7N, 20W
SAP 33 35	7N, 17W
SAP 33 36	7N, 16W
SAP 33 37	9N,18W; 7N,18W; 6N,18W
SAP 33 38	6N, 16W
SAP 33 39	9N, 18W
SAP 33 41	5N, 19W
SAP 33 43	7N, 17W
SAP 33 44	7N, 17W
SAP 33 45	5N, 19W
SAP 33 46	8N, 18W
SAP 33 47	8N, 18W
SAP 33 48	7N,18W; 7N,16W
SAP 33 49	9N, 18W
SAP 33 50	7N, 19W

LSBP 33 1	6N,19W; 6N,18W; 7N,17W
LSBP 33 2	7N, 19W
LSBP 33 3	8N,18W; 7N,18W
LSBP 33 4	7N,19W; 6N,17W; 6N,18W
LSBP 33 5	6N,19W; 7N,17W
LSBP 33 6	8N,19W; 6N,17W
LSBP 33 7	7N,19W; 6N,19W
LSBP 33 8	6N, 19W
LSBP 33 9	6N, 17W
LSBP 33 10	8N, 18W
LSBP 33 11	7N, 17W
LSBP 33 12	6N, 18W
LSBP 33 14	6N, 17W
LSBP 33 15	6N, 18W
LSBP 33 16	6N, 17W
LSBP 33 17	6N, 18W
LSBP 33 18	6N, 18W
LSBP 33 19	6N, 17W
LSBP 33 20	ERBR
LSBP 33 21	7N, 19W
LSBP 33 22	9N, 20W

BR 0033 5 B	8N,18W
BR 0033 6 B	7N, 19W
BR 0033 8 B	7N, 19W
BR 0033 9 BO	6N, 17W
BR 0033 10 B	7N, 17W
BR 0033 11 B	5N, 19W
BR 0033 12 BO	6N,19W; 7N,20W
BR 0033 13 B	7N, 17W
BR 0033 16 B	8N, 19W
BR 0033 17 B	9N, 18W
BR 0033 18 B	7N, 19W
BR 0197 7 B	6N, 17W
ER 0033 15 B	Debris
ER 0206 4 B	9N, 18W
ER 1213 1 B	8N, 19W
ER 1247 1 B	Plans not found-Nov 2025
ER 1265 4 B	Plans not found-Nov 2025
ER 78 1	Debris
RS 0197 3 B	Plans not found-Nov 2025
RS 0197 5 B	6N, 17W
RS 0325 9 B	8N, 18W
RS 1265 3 B	6N, 19W
S 191 2 1	5S, 19W
S 0194 1 B	7N, 18W
S 0194 2 B	7N, 18W
S 0197 2 B	7N, 17W
S 208 2 2	9N, 18W
S 0208 3 B	9N, 19W
S 0289 1 B	6N, 18W
S 0289 2 B	6N, 18W
S 0290 4 B	5N, 19W
S 0290 5 B	5N, 19W
S 0290 9 B	5N, 19W
S 0325 3 B	8N, 18W
S 1212 1 B	9N, 19W
S 1212 2 B	9N, 19W
S 1212 3 B	9N, 19W
S 1212 4 B	8N, 18W
S 1265 1 B	7N, 19W
S 1265 2 B	7N, 19W
STP 0033 14 BO	7N,18W; 9N,18W
STP 0197 10 B	7N, 17W
STP 1247 2 B	6N, 17W
STPBR 1247 3 B	6N,17W
STP 2157 1 B	7N, 19W
STPBR 0290 13 BO	Plans not found-Nov 2025
PMS SRS RS 000S 033 B	Stripe