



- BR-0042(9)B Federal Aid Project No.
- SAP-42(62) State Aid Project number
- LSBP-42(9) LSBP Project number
- LSRP-42(1) LSRP Project number
- State Aid Route
- State Aid Project
- Federal Aid Route
- State Hwy
- Supervisor District (2023)

Revised: 5-18-2026
Leflore County

SAP BI 42 1	Posting
SAP 42 1	19N, 1W
SAP GC 42 1	22N, 1W
SAP 42 1 M	Stripe
SAP 42 1 S	Reseal
SAP 42 2	19N, 1E
SAP 42 2 M	18N, 1W
SAP 42 2 S	Reseal
SAP 42 3	18N, 1W
SAP 42 3 M	Overlay
SAP 42 3 S	Reseal
SAP 42 4	22N, 1E
SAP 42 4 M	Stripe
SAP 42 4 S	Reseal
SAP 42 5	19N, 2W
SAP 42 5 M	19N, 1E & 2E
SAP 42 5 S	Reseal
SAP 42 6	22N, 1E
SAP 42 6 S	Reseal
SAP 42 7	17N, 2W
SAP 42 7 M	22N, 2W
SAP 42 7 S	Reseal
SAP 42 8	18N, 1E
SAP 42 8 S	Reseal
SAP 42 9	19N, 2W
SAP 42 9 S	Reseal
SAP 42 10	17N, 2W
SAP 42 10 S	Reseal
SAP 42 11	22N, 1W
SAP 42 11 S	Reseal
SAP 42 12	19N, 1E
SAP 42 12 S	Reseal
SAP 42 13	17N, 1W
SAP 42 13 S	Reseal
SAP 42 14 S	Reseal
SAP 42 15	21N, 2W
SAP 42 15 S	Reseal
SAP 42 16	19N, 1E
SAP 42 16 S	Reseal
SAP 42 17	18N, 1W
SAP 42 17 S	Reseal
SAP 42 18	19N, 1E
SAP 42 18 S	Reseal
SAP 42 19	21N, 1E
SAP 42 19 S	Reseal
SAP 42 20	18N, 1W
SAP 42 20 S	Reseal
SAP 42 22	18N, 2W
SAP 42 24	18N, 1E
SAP 42 26	19N & 20N, 1W & 2W
SAP 42 27	18N, 1E
SAP 42 28	22N, 1W
SAP 42 29	19N, 1W
SAP 42 30	19N, 1W
SAP 42 31	19N 20N & 21N, 1E
SAP 42 32	20N, 2W
SAP 42 33	20N, 1W
SAP 42 34	22N, 2W
SAP 42 35	19N, 1E
SAP 42 36	18N, 2W
SAP 42 37	18N, 1W
SAP 42 38	22N, 1W
SAP 42 39	21N, 1E
SAP 42 40	21N, 1E
SAP 42 41	21N, 1W
SAP 42 42	19N, 2W
SAP 42 43	20N, 2W
SAP 42 44	20N, 2W
SAP 42 45	20N, 1W
SAP 42 46	19N, 1W & 2W
SAP 42 47	18N, 1E
SAP 42 48	16N, 2W
SAP 42 49	18N, 2W
SAP 42 50	22N, 1E
SAP 42 51	19N, 1E & 2E
SAP 42 53	20N, 2W
SAP 42 57	20N, 2W
SAP 42 58	17N, 1W
SAP 42 60	19N, 1E
SAP 42 61	21N, 2W
SAP 42 62	22N, 1E
SAP 42 64	20N, 2W
SAP 42 65	18N, 1E
SAP 42 66	21N, 2W

LSBP 42 1	22N, 2W
LSBP 42 2	20N, 1W
LSRP 42 1	Overlay

BR 0042 9 B	20N, 2E
BR 0042 13 B	19N, 2E
BR 0042 22 B	18N, 1E
BR 0702 3 B	18N, 1E
BR 0708 5 B	21N, 1E
BR 1762 1 B	21N, 2E
BR 1765 1 B	18N, 2W
ER 0042 2 B	Plans not found
ER 0614 7 B	19N, 2W
ER 0705 1 B	21N, 1E
ER 0705 2 B	21N, 1E
ER 0708 7 B	20N, 1E
ER 0764 6 B	20N, 2E
MS129 0042 1 B	Overlay
PLH 0042 18 B	Eng
PLH 0042 18 BI	20N, 2E
RRO 0042 3 B	Location undetermined
RRP 0042 8 B	21N, 1E
RS 0614 5 B	19N, 2W
RS 0708 3 B	19N, 20N & 21N, 1E
RS 0778 3 B	22N, 1W & 2W
RS 1769 1 B	19N, 1W
RS 1769 2 B	19N, 1W
RS 0042 10 B	Stripe
S 0614 1 B	19N, 2W
S 0614 2 B	19N, 1W
S 0622 2 B	17N, 2W
S 0701 2 B	18N, 1E & 1W
S 0701 3 B	18N, 1E
S 0701 4 B	18N, 1W
S 0702 2 B	19N, 1E
S 0706 1 B	20N, 1E
S 0708 2 B	19N, 1E
S 0756 2 B	19N, 2E
S 0765 1 B	21N, 1W
S 0767 1 B	20N, 2W
S 0767 2 B	20N, 2W
S 0767 3 B	20N, 2W
S 0773 1 B	17N, 1E
S 0774 1 B	19N, 1E
S 0774 2 B	19N, 1E
S 0778 1 B	22N, 2W
S 1782 1 B	21N, 1E
S 1785 2 B	22N, 2W
S 1786 1 B	22N, 2W
S 1787 1 B	19N, 2W
S 1788 1 B	18N, 2W
S 702 2 1	19N, 2W
S 708 2 1	21N, 1E
S 756 2 1	19N, 2E
SR 0708 4 B	21N, 1E
SRS 0042 4 B	Eng
STP 0042 14 B	17N, 1E
STP 0042 17 B	20N, 1W ; 20N, 2W
STP 0083 1 B	Wetland
STP 0702 4 B	18N, 1W
STPBR 0042 23B	ERBR
PMS SRS RS 000S 042 B	Stripe
PMS 000S 142 B	Stripe