




BR-0054(9)B Federal Aid Project No.
 SAP-54(6)2 State Aid Project number
 LSBP-54(9) LSBP Project number
 LSRP-54(1) LSRP Project number

State Aid Route
 State Aid Project
 Federal Aid Route
 State Hwy
 Supervisor District (2024)

Revised: 2-3-2026
Panola County



SAP BI 54 1	Posting
SAP 54 1	8S, 7W
SAP 54 1 M	Several-stripe
SAP 54 1 S	10S,6W; 6S,9W
SAP 54 2	7S, 6W
SAP 54 2 M	9S, 9W
SAP 54 3	8S, 5W
SAP 54 3 M	10S, 7W
SAP 54 4	7S, 9W
SAP 54 4 S	Several
SAP 54 5	27N, 3E
SAP 54 5 M	9S,9W; 10S,6W
SAP 54 5 S	Several
SAP 54 6	6S, 6W
SAP 54 6 M	7S, 7W
SAP 54 6 S	Several
SAP 54 7	6S, 9W
SAP 54 7 M	7S, 7W
SAP 54 7 S	Several
SAP 54 8	9S,9W; 9S,8W
SAP 54 8 M	9S, 6W
SAP 54 8 S	Several
SAP 54 9	9S, 8W
SAP 54 9 M	10S, 6W
SAP 54 9 S	Several
SAP 54 10	7S, 6W
SAP 54 10 M	9S, 7W
SAP 54 10 S	Several
SAP 54 11	7S, 6W
SAP 54 11 M	27N,2E; 9S,9W
SAP 54 11 S	Several
SAP 54 12	27N, 2E
SAP 54 12 M	8S,7W
SAP 54 12 S	10S, 6W & 7W
SAP 54 13 S	6S,6W; 7S,6W; 6S,5W
SAP 54 14	9S,7W
SAP 54 14 S	7S, 6W
SAP 54 15	8S, 8W
SAP 54 15 S	10S, 6W
SAP 54 16	7S, 6W
SAP 54 18	9S, 8W
SAP 54 19	8S, 7W
SAP 54 20	6S, 7W
SAP 54 21	9S, 6W
SAP 54 22	9S, 8W
SAP 54 23	8S, 5W
SAP 54 24	7S, 6W
SAP 54 25	27N, 2E
SAP 54 26	27N, 3E
SAP 54 28	Several-overlay
SAP 54 32	9S, 7W
SAP 54 35	Several-overlay
SAP 54 36	6S,5W; 6S,7W; 7S,6W
SAP 54 38	9S,7W
SAP 54 39	7S, 7W
SAP 54 40	8S, 7W
SAP 54 41	9S, 8W
SAP 54 42	10S, 7W
SAP 54 43	7S, 6W
SAP 54 44	8S, 6W
SAP 54 45	8S, 6W
SAP 54 46	10S, 7W
SAP 54 47	7S,9W; 6S,8W
SAP 54 50	9S, 8W
SAP 54 51	9S, 7W
SAP 54 52	9S, 7W
SAP 54 54	6S, 8W
SAP 54 57	9S, 7W
SAP 54 58	7S, 7W
SAP 54 59	27N, 3E
SAP 54 60	8S, 9W
SAP 54 61	8S, 8W
SAP 54 62	10S, 8W
SAP 54 63	8S, 8W
SAP 54 65	7S & 8S, 7W
SAP 54 66	8S, 8W
SAP 54 67	Plans not found-Feb 2026

LSRP 54 1	10S, 8W
LSBP 54 1	7S,5W; 10S,7W; 10S,5W; 8S,7W
LSBP 54 2	7S,6W; 7S,9W; 10S,7W; 10S,7W
LSBP 54 3	7S,6W; 7S,9W; 10S,8W; 10S,6W; 9S,8W
LSBP 54 4	7S,6W; 7S,8W; 27N,2E; 9S,5W; 9S,7W
LSBP 54 5	7S,6W; 8S,9W; 27N,3E; 10S,6W; 8S,8W
LSBP 54 6	9S,6W; 8S,7W
LSBP 54 7	7S,5W; 27N,3E; 9S,6W; 9S,7W
LSBP 54 8	8S,6W; 10S,7W; 8S,6W
LSBP 54 9	7S,6W; 8S,9W; 10S,7W; 9S,6W; 8S,8W
LSBP 54 10	7S, 9W
LSBP 54 11	6S, 6W
LSBP 54 12	8S, 6W
LSBP 54 14	6S, 9W
LSBP 54 15	9S, 6W
LSBP 54 16	9S, 7W
LSBP 54 17	10S, 7W
LSBP 54 18	7S, 8W
LSBP 54 19	10S, 5W
LSBP 54 20	7S, 7W
LSBP 54 21	27N, 2E
LSBP 54 22	6S, 6W
LSBP 54 24	7S, 9W
LSBP 54 25	10S, 5W
LSBP 54 26	10S, 6W
LSBP 54 27	8S, 7W
LSBP 54 28	7S, 8W
LSBP 54 29	8S, 8W
LSBP 54 30	Plans not found-Feb 2026
LSBP 54 31	Plans not found-Feb 2026
LSBP 54 32	10S, 6W

AHL 0054 8 B	8S, 5W
BR 0054 20 B	9S, 7W
BR 0054 21 BO	6S,9W; 8S,6W; 9S,7W
BR 0054 22 BO	6S,6W; 6S,8W; 9S,8W
BR 0054 23 B	6S, 8W
BR 0054 24 B	8S, 6W
BR 0054 27 B	6S, 6W
BR 0054 28 BO	6S, 6W
BR 0054 29 B	27N, 2E
BR 0054 30 BO	10S, 3E
BR 0054 31 B	10S, 6W
BR 0054 32 BO	7S, 8W
BR 0054 34 B	10S, 7W
BR 0054 36 BO	9S, 6W
BR 0839 3 B	9S, 7W
BR 0839 4 B	9S, 7W
BR 0840 6 B	9S, 8W
BR 0842 2 B	8S, 7W
DS 0885 2 B	8S, 8W
EFL 0054 37 BO	8S, 5W
EHS S 0840 2 B	9S, 9W
HRRR 0054 35 B	6S & 7S & 8S, 7W
HRRR 0837 4 B	9S, 8W
HRRR 0840 7 B	9S, 8W & 9W
MS 027 054 1 B	7S, 9W
MS 027 054 2 B	7S, 9W
RRP 0054 11 B	6S, 7W
RRP 0054 12 B	9S, 7W
RRP 0054 19 B	9S, 7W
RS 0840 4 B	9S, 9W
RS 1841 1 B	6S, 8W
RS 1841 4 B	7S, 8W
RS 1843 4 B	10S, 6W
RS 1843 5 B	10S, 5W
S 0834 7 B	7S, 6W
S 0836 4 B	27N, 3E
S 0839 1 B	9S, 7W
S 0839 2 B	10S, 6W
S 0885 3 B	8S, 9W
S 1842 1 B	9S, 9W
S 1843 1 B	10S, 5W
S 1843 2 B	10S, 7W
S 1843 3 B	10S, 6W
S 837 2 1	9S, 8W
SRS 0054 6 B	Eng
STP 0054 25 B	6S, 8W
STP 0054 26 BO	6S, 6W
STP 0839 5 B	9S, 7W
STP 1841 3 B	8S, 8W
STP 1841 5 B	8S, 8W
STPBR 0054 39B	ERBR
PMS SRS RS 0005 054 B	Stripe