



State Aid Route  
 State Aid Project  
 Federal Aid Route  
 State Hwy  
 Supervisor District

Revised: 4-23-2026  
**Perry County**

Federal Aid Project No.  
 State Aid Project number  
 LSBP Project number  
 LSRP Project number

SAP BI 56 1	Posting
SAP 56 1	Plans not found-Feb 2026
SAP 56 1 M	5N, 10W
SAP 56 1 S	Several
SAP 56 2	2N, 10W
SAP 56 2 M	5N,11W; 4N,10W; 4N,11W
SAP 56 2 S	5N,10W; 3N,10W
SAP 56 3	3N, 10W
SAP 56 3 M	Several-stripe
SAP 56 3 S	1S,10W; 2N,10W
SAP 56 4	4N, 9W
SAP 56 4 S	5N,11W; 3N,11W
SAP 56 5	1S, 10W
SAP 56 5 M	5N,10W; 5N,9W; 3N,9W
SAP 56 5 S	Several
SAP 56 6	2N, 10W
SAP 56 6 M	5N,11W; 5N,10W
SAP 56 6 S	4N,11W; 4N,10W
SAP 56 7	1N, 11W
SAP 56 7 M	3N, 11W
SAP 56 7 S	Several
SAP 56 8	4N, 11W
SAP 56 8 M	5N, 11W
SAP 56 8 S	Several
SAP 56 9	3N, 11W
SAP 56 9 M	Plans not found-Feb 2026
SAP 56 9 S	Several
SAP 56 10	5N, 9W
SAP 56 10 S	Several
SAP 56 11 M	5N,10W; 5N,11W; 4N,11W; 5N,9W; 4N,9W; 1S,9W; 1S,10W
SAP 56 11 S	Several
SAP 56 12	1N, 11W
SAP 56 12 M	Plans not found-Feb 2026
SAP 56 12 S	Several
SAP 56 13	4N, 10W
SAP 56 13 S	Several
SAP 56 14	4N, 11W
SAP 56 14 S	Several
SAP 56 15 S	Several
SAP 56 16 S	Several
SAP 56 17 S	Several
SAP 56 18	2N, 9W
SAP 56 20	1N, 11W
SAP 56 21	5N, 9W
SAP 56 22	5N, 9W
SAP 56 24	4N, 10W
SAP 56 25	5N, 9W
SAP 56 26	2N, 9W
SAP 56 27	1N, 11W
SAP 56 28	5N, 10W
SAP 56 29	2N, 9W
SAP 56 32	4N, 9W
SAP 56 33	5N, 11W
SAP 56 35	1S, 10W
SAP 56 36	4N, 10W
SAP 56 38	1S, 9W
SAP 56 39	5N, 9W
SAP 56 41	4N, 10W
SAP 56 42	5N, 10W
SAP 56 43	4N, 10W
SAP 56 44	5N, 10W
SAP 56 45	3N, 9W
SAP 56 46	1S, 10W
SAP 56 49	3N, 9W
SAP 56 50	3N,11W; 4N,10W
SAP 56 51	5N, 9W
SAP 56 52	3N, 9W
SAP 56 53	1S, 9W
SAP 56 55	3N, 10W
SAP 56 56	4N, 10W
SAP 56 58	5N, 9W
SAP 56 59	3N, 11W
SAP 56 60	4N, 11W
SAP 56 61	5N, 11W
SAP 56 62	1S, 9W
SAP 56 63	1S,10W; 1N,11W
SAP 56 64	1S,11W; 5N,9W
SAP 56 65	5N, 10W
SAP 56 68	5N, 9W

LSBP 56 1	2N, 9W
LSBP 56 2	3N, 11W
LSBP 56 3	1N,11W; 4N,11W; 3N,9W
LSBP 56 4	5N, 11W
LSBP 56 5	1N,11W; 4N,11W; 1S,11W; 5N,11W; 1N,11W; 5N,11W
LSBP 56 6	1S, 10W
LSBP 56 7	4N, 9W
LSBP 56 8	2N,9W; 1S,11W
LSBP 56 9	1S, 10W
LSBP 56 10	3N, 11W
LSBP 56 11	3N, 9W

BR 0056 10 B	5N, 10W
BR 0056 12 B	1S, 11W
BR 0056 15 B	1N, 9W
BR 0056 19 B	4N, 11W
BR 0056 25 B	4N, 9W
BR 1151 2 B	2N, 10W
BR 1153 4 B	5N, 10W
BR 1257 4 B	3N, 10W
BR 1257 5 B	3N, 10W
DECD 0056 16 B B	5N, 10W
DECD 0056 16 B A	3N, 11W
DECD 0056 16 B C	3N, 10W
DS 1153 2 B	5N, 10W
EFLH 0056 20 BO	1N, 10W
EFLH 0056 21 BO	1N, 11W
EFLH 0056 22 B	1N, 9W
EFLH 0056 23 BO	1S, 10W
EFLH 1159 4 B	1N, 11W
EHS S 1257 2 B	3N, 9W
ER 0056 4 B	Plans not found-Feb 2026
ER 0056 8 B	Plans not found-Feb 2026
ER 0056 18 B	Plans not found-Feb 2026
ER 59 1	1S, 10W
ER 59 2	3N, 10W
ER 59 3	5N, 11W
ER 1153 6 B	Plans not found-Feb 2026
ER 1153 7 B	Plans not found-Feb 2026
ER 1165 5 B	4N, 10W
MS135 056 1 B	4N, 10W
MS135 056 3 B	4N, 10W
RRP 0056 13 B	2N, 9W
RRP 0056 14 B	2N, 9W
RRP 1257 3 B	3N, 10W
RS 0223 5 B	3N, 11W
RS 0276 3 B	3N, 10W
RS 0276 4 B	3N, 11W
RS 1150 2 B	5N, 9W
RS 1151 1 B	2N, 10W
RS 1153 5 B	5N, 10W
RS 1165 1 B	4N, 10W
RS 1165 2 B	4N, 10W
RS 1253 2 B	3N, 11W
RS 1280 3 B	5N, 9W
S 0223 1 B	3N, 11W
S 0260 1 B	3N, 9W
S 0260 3 B	3N, 9W
S 0260 4 B	3N, 9W
S 0276 1 B	4N, 10W
S 0276 2 B	3N,11W; 4N,10W&11W
S 1153 3 B	5N, 10W
S 1224 1 B	5N, 11W
S 1253 1 B	4N, 11W
S 1257 1 B	4N, 9W
S 1280 1 B	5N, 9W
S 1280 2 B	5N, 9W
S 259 2 1	1S, 10W
STP 0056 24 B	3N&4N,10W; 5N,10W
STP 1153 5 B	5N, 10W
STP 1165 3 B	4N, 10W
PMS SRS RS 0005 056 B	Stripe
PMS 0005 156 B	Stripe