



	State Aid Route		Federal Aid Project No.
	State Aid Project		State Aid Project Number
	Federal Aid Route		LSBP Project Number
	State Hwy		LSRP Project Number
	Supervisor District		

Revised: 3-31-2026
Simpson County

SAP BI 64 1	Posting
SAP 64 1	2N, 2E
SAP 64 1 M	2N, 1E
SAP 64 1 S	1N,6E; 10N,21W
SAP 64 2	10N, 21W
SAP 64 2 M	2N, 4E
SAP 64 2 S	Several
SAP 64 3	1N, 6E
SAP 64 3 S	Several
SAP 64 4	2N, 4E
SAP 64 4 M	1N, 17W
SAP 64 4 S	9N,20W; 2N,1E
SAP 64 5	2N, 5E
SAP 64 5 M	1N, 6E
SAP 64 5 S	Several
SAP 64 6	2N, 1E
SAP 64 6 M	2N, 3E
SAP 64 6 S	Several
SAP 64 7	2N, 1E
SAP 64 7 M	Several-stripe
SAP 64 7 S	Several
SAP 64 8	2N, 2E
SAP 64 8 M	2N, 4E
SAP 64 8 S	Several
SAP 64 9	10N, 2E
SAP 64 9 S	2N,3E; 1N,2E
SAP 64 10	1N, 2E
SAP 64 10 S	10N, 18W
SAP 64 11	1N, 3E
SAP 64 11 M	2N, 1E
SAP 64 11 S	Several
SAP 64 12	1N, 6E
SAP 64 12 M	10N, 17W
SAP 64 12 S	Several
SAP 64 13	2N, 1E; 2N,2E
SAP 64 13 M	2N, 1E
SAP 64 13 S	Several
SAP 64 14	10N, 19W
SAP 64 14 M	Several-stripe
SAP 64 14 S	Several
SAP 64 15	2N, 5E
SAP 64 15 M	10N, 17W
SAP 64 15 S	Several
SAP 64 16	1N, 1E
SAP 64 16 M	10N,19W; 2N, 4E
SAP 64 16 S	Several
SAP 64 17	10N, 21W
SAP 64 17 M	Plans not found-Mar 2026
SAP 64 17 S	Several
SAP 64 18	2N, 2E
SAP 64 18 S	Several
SAP 64 19 S	Plans not found-Mar 2026
SAP 64 20	1N, 5E
SAP 64 22	10N, 18W
SAP 64 23	2N, 4E
SAP 64 24	1N, 6E
SAP 64 25	1N, 1E
SAP 64 26	1N, 6E
SAP 64 27	1N, 2E
SAP 64 28	2N, 3E
SAP 64 29	1N, 6E
SAP 64 30	9N, 20W
SAP 64 31	1N, 2E
SAP 64 32	1N & 10N, 17W
SAP 64 33	10N, 18W
SAP 64 34	2N, 2E
SAP 64 35	2N, 4E
SAP 64 36	1N, 4E
SAP 64 37	1N, 6E
SAP 64 38	10N,21W; 2N,2E
SAP 64 39	10N,18W; 10N,17W
SAP 64 41	2N, 4E
SAP 64 44	1N, 5E
SAP 64 45	1N, 5E

SAP 64 46	2N, 6E
SAP 64 47	10N, 17W
SAP 64 48	2N, 4E
SAP 64 49	1N, 5E
SAP 64 50	1N, 6E
SAP 64 52	10N, 21W
SAP 64 53	1N, 2E
SAP 64 54	1N, 6E
SAP 64 55	10N, 17W
SAP 64 56	10N, 11E
SAP 64 57	1N, 2E
SAP 64 58	2N, 2E
SAP 64 60	1N, 6E
SAP 64 61	1N, 5E
SAP 64 62	2N, 2E
SAP 64 64	Plans not found-Mar 2026

LSBP 64 1	10N,17W; 2N,6E
LSBP 64 2	1N,21W; 10N,20W
LSBP 64 3	1N, 6E
LSBP 64 4	2N, 5E
LSBP 64 5	10N,17W; 1N,6E
LSBP 64 6	10N, 18W
LSBP 64 7	1N, 5E
LSBP 64 8	10N, 17W
LSBP 64 9	2N,4E; 1N,6E; 1N,5E
LSBP 64 10	2N, 2E
LSBP 64 11	1N, 4E
LSBP 64 12	2N, 3E
LSBP 64 13	2N, 6E
LSBP 64 14	1N, 4E
LSBP 64 15	9N, 18W
LSBP 64 16	1N, 5E
LSBP 64 17	2N, 5E
LSBP 64 18	1N, 4E
LSBP 64 19	10N, 17W
LSBP 64 20	10N, 20W
LSBP 64 21	1N, 6E
LSBP 64 22	10N, 19W
LSBP 64 23	Plans not found-Mar 2026
LSBP 64 24	2N, 3E

BR 0064 9 B	1N, 2E
BR 0064 11 B	2N, 5E
BR 0064 13 B	9N, 18W
BR 0064 14 B	2N, 3E
BR 0064 16 B	1N, 4E
BR 0064 17 B	1N, 4E
BR 0064 18 BO	2N, 4E
BR 0064 19 B	2N, 5E
BR 0319 11 B	10N, 21W
BR 0390 5 B	1N, 3E
BR 0392 3 B	10N,20W; 10N,18W
BR 0392 4 B	10N, 18W
BR 1329 3 B	10N, 17W
BR 0392 5 B	Plans not found-Mar 2026
ER 0064 2 B	Plans not found-Mar 2026
ER 0064 20 B	Plans not found-Mar 2026
ER 0319 7 B	1N, 2E
ER 0350 8 B	10N, 17W
ER 0390 4 B	Plans not found-Mar 2026
HRRR 0064 21 B	Several-stripe
HRRR 0321 4 B	2N, 4E
HRRR 0326 4 B	1N & 2N, 6E
RRP 0064 12 B	1N, 5E
RRP 0393 3 B	10N, 17W
RS 0319 6 B	1N, 1E
RS 0319 8 B	10N, 21W
RS 0319 9 B	10N, 21W
RS 0320 4 B	2N, 3E
RS 0320 5 B	2N, 3E
RS 1329 2 B	10N, 17W
S 0319 1 B	10N, 21W
S 0319 2 B	10N, 21W
S 0319 3 B	9N, 21W
S 0319 5 B	Plans not found-Mar 2026
S 0320 3 B	2N, 3E
S 0321 3 B	2N, 4E
S 0326 1 B	1N, 6E
S 0326 2 B	1N, 6E
S 0350 2 B	10N, 19W
S 0350 3 B	10N, 17W
S 0350 4 B	10N, 19W
S 0350 7 B	10N, 17W
S 0388 1 B	1N, 4E
S 0388 2 B	1N, 4E
S 0390 1 B	2N, 4E
S 0390 2 B	1N, 3E
S 0390 3 B	1N, 3E
S 0392 1 B	10N, 20W
S 0392 2 B	10N, 20W
S 0393 1 B	10N, 17W
S 0393 2 B	10N, 17W
S 0426 12 B	2N, 2E
S 1325 1 B	2N, 5E
S 1325 2 B	2N, 5E
S 1329 1 B	1N, 5E
S 320 2 1	2N, 3E
S 323 2 1	2N, 5E
S 350 2 1	10N, 19W
STP 0083 1 B	Wetland
STP 0319 13 B	2N, 2E
STP 0320 10 B	2N, 3E
STP 0326 3 B	1N, 6E
STP 0326 5 B	1N, 17W
STP 0393 4 B	10N, 17W
STP 0393 5 B	10N, 17W
STP 0426 17 B	2N, 3E
STPBR 0064 22B	2N, 3E
STPBR 0064 23B	ERBR
STPD 0393 6 B	10N, 17W
PMS SRS RS 000S 064 B	Stripe
PMS 000S 164 B	Stripe