



BR-0081(9)B Federal Aid Project No.
SAP-81(62) State Aid Project number
LSBP-81(9) LSBP Project number
LSRP-81(1) LSRP Project number

State Aid Route
State Aid Project
Federal Aid Route
State Highway
Supervisor District (2024)

Revised: 7-29-2025

Yalobusha County

SAP BI 81 1	Posting
SAP 81 1	25N & 11S, 4E
SAP 81 1 M	11S, 4W
SAP 81 1 S	Reseal
SAP 81 2	23N & 24N, 6E
SAP 81 2 M	Stripe
SAP 81 2 S	Reseal
SAP 81 3	24N, 7E
SAP 81 3 M	24N, 6E
SAP 81 3 S	Reseal
SAP 81 4	11S, 5W
SAP 81 4 M	10S & 11S, 5W
SAP 81 4 S	Reseal
SAP 81 5	24N, 7E
SAP 81 5 M	11S, 5W
SAP 81 5 S	Reseal
SAP 81 6	11S, 4W
SAP 81 6 M	Stripe
SAP 81 6 S	Reseal
SAP 81 7	24N, 4E
SAP 81 7 M	24N, 6E
SAP 81 7 S	Reseal
SAP 81 8	11S, 4W
SAP 81 8 M	11S, 4W
SAP 81 8 S	Reseal
SAP 81 9	23N, 7E
SAP 81 9 M	25N, 6E
SAP 81 9 S	Reseal
SAP 81 10	11S, 5W
SAP 81 10 M	25N, 5E
SAP 81 10 S	Reseal
SAP 81 11	23N, 7E
SAP 81 11 M	24N, 7E
SAP 81 11 S	Reseal
SAP 81 12	11S, 5W
SAP 81 12 M	11S, 5W
SAP 81 12 S	Reseal
SAP 81 13	11S, 4W
SAP 81 13 M	24N, 6E
SAP 81 13 S	Reseal
SAP 81 14	25N & 12S, 7E
SAP 81 14 S	Reseal
SAP 81 15	23N, 6E
SAP 81 15 M	Overlay
SAP 81 15 S	Reseal
SAP 81 16	25N & 12S, 5E
SAP 81 16 M	Plans not found
SAP 81 16 S	Reseal
SAP 81 17	25N & 12S, 7E
SAP 81 17 S	Reseal
SAP 81 18	11S, 4W
SAP 81 18 S	Reseal
SAP 81 19	25N, 5E
SAP 81 19 S	Reseal
SAP 81 20	25N, 5E
SAP 81 20 S	Reseal
SAP 81 21	25N, 6E & 7E
SAP 81 21 S	Reseal
SAP 81 22	10S, 4W
SAP 81 22 S	Reseal
SAP 81 23 S	Reseal
SAP 81 24 S	Reseal
SAP 81 26	25N, 4E
SAP 81 27	11S, 6W
SAP 81 28	24N, 4E
SAP 81 29	25N, 4E
SAP 81 30	25N, 8E
SAP 81 31	24N, 7E
SAP 81 32	25N, 4E
SAP 81 34	11S, 4W
SAP 81 35	24N, 4E

LSBP 81 1	25N, 7W ; 24N, 7E
LSBP 81 2	24N, 7E
LSBP 81 3	11S, 5W
LSBP 81 4	12S, 3W ; 24N, 5E
LSBP 81 5	24N, 5E
LSBP 81 6	24N, 7E
LSBP 81 7	24N, 4E
LSBP 81 9	25N, 7E
LSBP 81 11	25N, 5E
LSBP 81 12	11S, 5W
LSBP 81 13	24N, 4E
LSBP 81 14	26N, 4E
LSBP 81 16	25N, 7E
LSBP 81 17	26N, 7W
LSBP 81 18	24N, 4E
LSBP 81 19	11S, 3W
LSBP 81 20	24N, 6E

AHL 0081 10 B	24N, 7E
AHL 0081 11 B	24N, 7E
APL 0081 21 B	11S, 4W
BR 0081 7 B	25N, 6E
BR 0081 8 B	24N, 4E
BR 0081 9 B	11S, 3W
BR 0081 13 B	24N, 4E
BR 0081 15 B	11S, 4W
BR 0081 16 BO	24N, 7E
BR 0081 17 B	24N, 4E
BR 0081 18 B	25N, 6E
BR 0081 19 BO	24N, 7E
BR 0081 22 BO	25N, 4E
BR 0789 5 B	25N, 6E
BR 0789 6 B	25N, 7E
BR 0824 4 B	11S, 6W
BR 0988 2 B	25N, 7E
BR 1800 1 B	24N, 6E
BR 1800 2 B	Plans not found
BR 1802 1 B	25N, 6E
BR 1802 2 B	24N, 7E
ER 1779 1 B	Plans not found
ER 1779 2 B	Plans not found
ER 1800 2 B	24N, 7E
ER 1802 2 B	25N, 6E
RS 0789 4 B	25N, 6E
RS 0824 2 B	11S, 6W
RS 2786 2 B	26N, 4E
RSG 0081 12 B	Stripe
S 0786 1 B	24N, 6E
S 0786 3 B	24N, 4E
S 0787 3 B	24N, 4E
S 0789 2 B	25N, 6E
S 0789 3 B	25N, 7E
S 0808 1 B	10S & 11S, 4W & 5W
S 0824 1 B	25N & 11S, 6W
S 0988 1 B	11S, 4W
S 1803 1 B	11S, 5W
S 2786 1 B	25N & 26N, 4E
S 789 2 1	25N, 6E & 7E
SG 0786 2 B	24N, 4E
SRS 0081 2 B	Eng
STP 0081 20 B	11S, 5W
STP 0081 24 B	11S, 3W
STP 0081 25 B	26N, 6W
STP 0824 5 B	25N, 4E
STP 0988 3 B	24N, 7E
STP 1803 4 B	11S, 5W
STPBR 0081 26BO	25N, 7E
PMS SRS RS 0005 081 B	Stripe
PMS 000S 181 B	Stripe